

General Environmental Incident Summary

Incident: 77 **Date/Time Notice:** 9/5/2001 0815 **DEM Incident No:**

Responsible Party: Executive Air Taxi

Date Incident: 9/5/2001 **Time Incident:** 0030 **Duration:**

County: Burleigh **Twp:** 138 **Rng:** 80 **Sec:** 0 **Qtr:**

Lat: 46.76567 **Long:** -100.77370 **Method:** Derived from Twp Rng

Location Description: Spill occurred at the Bismarck Airport during plane re-fueling operations.;
AH - 10/16/2012 - Could be Section 10, 14, 15, 23.

Submitted By: Lance Loken

Affiliation:

Address:

City:

State:

Zip:

Received By: Gary Berreth

Contact Person:

Municipal Airport
Bismarck, ND 58501

Distance Nearest Occupied Building: 100 Feet

Type of Incident: airplane fuel tank overflow

Description of Released Contaminant: Jet "A"

Volume Spilled: 60.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance:

Reported to NRC: Unknown

Cause of Incident:

Faulty overflow shutoff on airplane wing allowed tank to overflow onto the airport runway apron.

Risk Evaluation:

Explosive conditions

of Fatalities:

of Injuries:

Affected Medium:

Potential Environmental Impacts:

Fuel was contained with absorbents and sand. Some fuel was washed into storm sewer during cleanup operations

Action Taken or Planned:

The Bismarck Fire Department, Environmental Health and Building Inspection Department and High Plains Consortium, Inc. responded to the spill. The majority of spilled fuel was picked up with absorbents and sand. Absorbents and sand (approximately 6 yds.) will be farmed at the Bismarck Landfill (contact: Mel Fischer). Some fuel escaped into the City storm sewer. Fire Department diluted fuel by washing down and adding water to storm sewer.

Wastes Disposal Location: Absorbents and sand will be farmed at the Bismarck landfill.

Agencies Involved: Local Fire Department

